

MOISTURE MEASUREMENT IN AGRICULTURE. SAFE STORAGE. NO DAMAGE. MORE YIELD.

Fast and precise moisture measurement with Humimeter devices for grain, biomass, straw/hay.

 **Schaller**
Messtechnik / humimeter.com



FS3 Whole Grain – Cereals
0–40% moisture, 0 °C to +40 °C



FL2 Hay – Straw
8–60% moisture, –20 °C to +120 °C



BLL Wood Chips (Best Seller)
10–50% moisture, –10 °C to +80 °C

GRUBATEC



MESS- UND REGELTECHNIK

Grubatec AG

Wölferstrasse 5 · CH-4414 Füllinsdorf

Tel. +41(0)55 617 00 80 · sales@grubatec.ch · www.grubatec.ch